

**Technical Advisory Bulletin:** TAB-06-0001

**Description:** M5830S-AP-60 access point requires firmware version 2.0r2 or greater for compatibility and successful association with M5580M-FSU subscriber unit

**Products Affected:** M5830S-AP-60  
M5580M-FSU

**Corrective Action:** Upgrade M5830S-AP-60 with firmware version 2.0r2 or greater.  
No firmware upgrade required for M5580M-FSU

**Notes:** M5830S-AP-60 firmware is downloadable at  
[www.trangobroadband.com/downloads](http://www.trangobroadband.com/downloads)

The upgrade procedure can be found in the Firmware Upgrade Procedure document bundled within the firmware package.

If the above corrective action does not resolve the problem, contact Trango Technical Support for further assistance.