

Technical Advisory Bulletin: TAB-06-0002

Description: In some circumstances when power is initially applied to the PT-9009 power supply while it is connected to the PoE Junction Box (JBOX-2) with the transceiver, the transceiver may not power up. In such cases, the transceiver will gain power by manually unplugging and re-plugging the power connector into the JBOX-2.

Products Affected: International Power Supply PT-9009

Corrective Action: The corrective action is as follows:

Manually unplug and re-plug the DC power connector to the JBOX-2

Request an RMA for the power supply at
www.trangobroadband.com/psr

Notes: The power supply can be identified by the following print on the label:
TECHNICS MODEL NO.: TESA1-240075