

Technical Advisory Bulletin: TAB-06-0003

Description: Configuring the M5580S-SU for SU-SU communications is not supported. Enabling SU-SU communications on an M5830-AP with M5580 subscribers will cause loss of association with all subscribers, regardless of model.

Products Affected: M5580S-SU Atlas Fox

Corrective Action: Do not enable SU-SU communications if there are M5580 subscribers in the sector.

Notes: ○ There are no future plans to implement SU-SU support with the M5580 subscribers