

**Technical Advisory Bulletin:** TAB-06-0004

**Description:** The M5580S-FSU randomly reboots

**Products Affected:** Atlas FOX, M5580M-FSU

**Special Circumstances:** No specific circumstances will cause the unit to reboot

**Corrective Action:** Downgrade firmware from 2.0r11 to 2.0r10. Firmware currently available on the beta page of the website.

- Notes:**
- We are currently evaluating a new firmware code which will be released in the near future.
  - The new code will have all the features of 2.0r11 and new updates.